



## Firmware Update (version 8.17) for Pioneer CD Receivers

August 3, 2017

**Dear Valued Pioneer Customer:**

We would like to inform you of the availability of a firmware update (version **8.17**) for the current lineup of Pioneer CD receivers. **This firmware update is only for the following Pioneer CD Receivers sold in Australia and New Zealand: DEH-X1950UB, DEH-X2950UI, DEH-X3950BT, DEH-X4950BT, MVH-X195UI and MVH-X395BT.**

**Warning:** Installation on any other product could cause irreversible damage.

This firmware update (version **8.17**) contains the following improvements:

**- Fix following problems**

\*Corrects error when connecting certain smart phones running Android 6.0 to the Pioneer receiver.

**In order to perform this update, the following items are needed:**

- Pioneer Receiver model listed above
- Blank USB storage device (no file), 2 GB or larger in capacity, formatted to FAT32

Steps to install the firmware are attached. Installation of the update should take no more than ten minutes to complete.

**How to Obtain the Free Firmware Update:**

1. Download the firmware update files to a computer from the Pioneer website:  
<https://www.pioneer.com.au/firmwaresoftware/>
2. Transfer the files to the USB storage device for insertion into the Pioneer CD Receivers.

### Questions

If you have any questions, please contact Pioneer Customer Service on 1 800 672 102, Monday through Friday, 9:00 AM – 5:00 PM, excluding holidays.

Sincerely,

**Pioneer Electronics Australia Pty Ltd.**