

Firmware Update (version 8.15) for Pioneer CD Receivers

September 12, 2018

Dear Valued Pioneer Customer:

We would like to inform you of the availability of a firmware update (version 8.15) for the current lineup of Pioneer CD receivers. This firmware update is only for the following Pioneer CD Receivers sold in Australia & New Zealand: DEH-S5050BT, DEH-S4050BT, FH-S705BT, MVH-S405BT and MVH-S305BT.

Warning: Installation on any other product could cause irreversible damage.

This firmware update (version **8.15**) contains the following improvements:

- Fix following problems
 - *The receiving volume of particular smart phone becomes small when talking on the phone connected to a CD Receiver with BT.
 - *The phone number will not be displayed on a CD Receiver when a contact information in a phone's address book contains a photo/image.
 - *It did not support several types of Bluetooth playback of some smart phones (Android Ver. 8).

In order to perform this update, the following items are needed:

- Pioneer CD Receivers, DEH-S5050BT, DEH-S4050BT, FH-S705BT, MVH-S405BT or MVH-S305BT
- Blank USB storage device (no file), 2 GB or larger in capacity, formatted to FAT32

Steps to install the firmware are attached. Installation of the update should take no more than ten minutes to complete.

How to Obtain the Free Firmware Update:

- 1. Download the firmware update files to a computer from the Pioneer website: https://www.pioneer.com.au/firmwaresoftware/
- 2. Transfer the files to the USB storage device for insertion into the Pioneer CD Receivers.

Questions

If you have any questions, please contact Pioneer Technical support on 1800 988 268, Monday through Friday, 9:00 AM - 5:00 PM (excluding holidays).

Pioneer Electronics Australia Pty Ltd.