



Firmware Update for Certain Pioneer In-Dash AV Receivers

January 28th, 2020

Dear Valued Pioneer Customer:

We would like to inform you of the availability of a firmware update for **only the following Pioneer In-Dash AV Receivers sold in Australia and New Zealand**. Installation on any other product could cause irreversible damage.

MVH-Z5050BT
AVH-ZL5150BT
DMH-Z5150BT
AVH-Z5100DAB
AVH-Z5150BT
AVH-Z3100DAB
AVH-Z2150BT
AVH-Z7150BT

This firmware update corrects the following matter.

- Fixed the problem that there is no sound from rear speakers after finishing a call.

To perform this update, the following items are needed:

- Pioneer In-Dash AV Receiver
- Blank USB storage device (no files), 2 GB or larger in capacity, formatted to FAT32

Instructions on installing the firmware are provided on the same page as the firmware update. Installation of the update should take no more than ten minutes to complete.

How to Obtain the Free Firmware Update:

1. Download the firmware update files to a computer from the Pioneer website:
<https://www.pioneer.com.au/firmwaresoftware/>
2. Transfer the files to the USB storage device for insertion into the Pioneer In-Dash AV Receiver.

Questions

If you have any questions, please contact Pioneer Technical Support on 1800 988 268, Monday through Friday, 9:00 AM - 5:00 PM, excluding holidays.

Sincerely,

Pioneer Electronics Australia Pty Ltd.