



Firmware Update (version 1.01) for Pioneer In-Dash Navigation AV Receivers

November 8th, 2018

Dear Valued Pioneer Customer:

We would like to inform you of the availability of a firmware update (version 1.01) for the below listed Pioneer In-Dash Navigation AV Receivers. **This firmware update is only for the following Pioneer In-Dash Navigation AV Receivers sold in Australia and New Zealand: AVIC-Z910DAB & AVIC-Z710DAB.**

Warning: Installation on any other product could cause irreversible damage.

This firmware update (version 1.01):

- Adapt to Google Android Auto specification changes (AVIC-Z910DAB)
- Minor bug fixes

In order to perform this update, the following items are needed:

- Pioneer AVIC-Z910DAB or AVIC-Z710DAB In-Dash Navigation AV Receiver
- Blank USB storage device (no files), 2 GB or larger in capacity, formatted to FAT32

Steps to install the firmware are available on our website. Installation of the update should take no more than ten minutes to complete.

How to Obtain the Free Firmware Update:

1. Download the firmware update files to a computer from the Pioneer website:
<https://www.pioneer.com.au/firmwaresoftware/>
2. Transfer the files to the USB storage device for insertion into the Pioneer In-Dash Navigation AV Receiver.

Questions

If you have any questions, please contact Pioneer Technical Support at 1800 988 268, Monday through Friday, 9:00 AM - 5:00 PM, excluding holidays.

Sincerely,

Pioneer Electronics Australia Pty Ltd.